

Product Update: SCOTT® Roll Towel Dispenser Code 4941

To accommodate the increased roll length of SCOTT® Roll Towel Code 44199, some existing 4941 dispensers will require a new spindle. Any 4941 dispensers with the old Kimberly-Clark Professional logo on the cover and plastic spindles on the inside (figures 1 & 2) will need their spindles (figure 3) replaced.

The new spindle (figure 4) is available for free by contacting Customer Care:

AUS 1800 647 994
NZ 0800 447 814
kcp.au@kcc.com

All 4941 dispensers with the new kite logo on the front (figure 5), or with metal bar mechanism inside (figure 6) require no further action.



FIGURE 1: Old 4941 Roll Towel Dispenser



FIGURE 2: Old 4941 Dispenser (inside view)



FIGURE 3: Old 4941 Spindle
NEEDS TO BE REPLACED




FIGURE 4: New 4941 Spindle



FIGURE 5: New 4941 Roll Towel Dispenser
NO ACTION REQUIRED



FIGURE 6: Old 4941 metal bar Dispenser
NO ACTION REQUIRED

